






- 1. LUBE O-RING BEFORE ASSEMBLY W/PETROLEUM JELLY OR VASELINE
- 2. ALL METAL FITTINGS SHOULD BE ASSEMBLED USING THREAD SEALANT LOCTITE 567 OR EQUIVALENT.
- 3. LEAK TEST WITH AIR TO 80 PSIG +/-2
- 4. PLACE BROCHURE #73309 IN PLASTIC BAG WITH DRAIN VALVE AND
- THEN PLACE INTO SHIPPING CARTON
- 6. TORQUE SCREWS AT 20 IN-LB (ITEM 8).
- 7. COMPLETE UNIT WEIGHS APPROX. 85#
- 8. CASTING HEAD & FLANGE POWDER COAT MARINE WHITE
- 9. BOWLS POWDER COAT MARINE WHITE
- 10. PART #73301000 INCLUDES CASTING HEAD, 2 FLANGES #73301001
- AND (6) BOLTS #73308.





_														
	<b>REVISE O</b>	NLY ON Pro	/E SYSTEM	DRAWN	ACS	DATE 112410					PARKER HANNIFIN		Ν	WIP
	THIS PRINT SUPERSEDES ANY EARLIER DATE; DESTROY SAM			Еснеск	JKN	070811			( - 1 )	Racor	805 NORTH WEST S HOLLY SPRINGS, M			≥
	THIS PRINT AND ALL INFORMATION MATERIAL:		DESIGN	ACS	112410	TITLE							e<	
	CONFIDENTIAL AND MUST NOT BE MADE PUBLIC OR COPIED UNLESS AUTHORIZED BY US. THIS PRINT IS SUBJECT TO RETURN ON DEMAND.			UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES		DUAL FBO MARINE FILTER ASM								
	PROD CODE 56014		DECIMAL	.1	ANGULAR		_						Ver	
			FINISH:	.XX=± .06	1	±	SIZE	CODE IDE	NT NO.	DWG. NO.			REV	-
	NEXT ASSY	FIRST USED ON	WHITE POWDER COAT	XXX- +	030 <sup>fr.</sup>	ACTIONAL ±	D	557	52	DF	BO-14-I	MA	E	>
	APPLICA	TION		DO NOT SCA	LE DRAV	/ING	SCALE	0.375	DRAWING D	ATE		SHEET 1	ି <b>2</b>	Rev



	QUANTITY	REQD		PART NUMBER		DESCRIPTION							
						PARTS LIST							
	DRAWN	ŀ	ACS	DATE 112410				RACOR DIVISIO			∟		
TROY SAM	ECHECK		JKN	070811				805 NORTH WE HOLLY SPRINC			MIP		
	DESIGN		JKN	070811	TITLE						e<		
	UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES				DUAL FBO MARINE FILTER ASM								
	TOLERANCES DECIMAL ANGULAR						NT NO	DWG. NO.		REV	Ver		
	.XX= .XXX=	±010 .5 ± .005	FRA	± ACTIONAL ±		557	-	DFBO-14	4-MA	E	>		
	DO NO	T SCALE [	DRAW	/ING	SCALE	0.375	DRAWING D	ATE	SHEET 2	2	Rev		
					•				•				

ON OUTSIDE OF CARTON 5. WAREHOUSE/SHIPPING TO BAND BOX TO PALLET

NOTES:
1. USE (2) M8 X 2 3/4" HEX LAG BOLTS AND
WASHERS TO ATTACH DFBO TO CRATE.
2. PARTICLEBOARD SHEET TO SIT ON
TOP OF CRATE AS SHOWN
3. TAPE FLAPS CLOSED
4. USE 6" X 4" THERMAL TRANSFER LABEL

		REVISIONS				
Γ	.TR	DESCRIPTION	E. N.	DATE	DRN	СНК
	Е	SEE SHEET 1 FOR DETAILS	00305	051812	JN	JN