



PENN REPAIR BULLETIN

SEPTEMBER 9, 2009

For all 155L, 160L, 180L and
209M manufactured in 2007 and before

REPLACING MAIN GEAR and PINION GEAR

When replacing either the Main Gear, (005 155) or the Pinion Gear, (013 155). You MUST replace BOTH gears at the same time with Replacement Kit 005C209.

The Replacement Kit 005C209 contains (1) 005 209LC Main Gear and (1) 013 209LC Pinion Gear.

The gear ratio was changed from 2.8/1 to 3.2/1.

Attempting to mix 155 and 209LC gears will result in damage to both gears.